
Meridian 1

QPC422 Tone Detector Card

Description

Document Number: 553-2001-191

Document Release: Standard 4.0

Date: December 1995

© 1990, 1995

All rights reserved

Printed in the United States of America

Information is subject to change without notice. Northern Telecom reserves the right to make changes in design or components as progress in engineering and manufacturing may warrant. This equipment has been tested and found to comply with the limits for a Class A digital device pursuant to Part 15 of the FCC rules.

SL-1 and Meridian 1 are trademarks of Northern Telecom.

Revision history

July 31, 1990

Standard, release 1.0. Reissued for compliance with Northern Telecom standard 164.0.

December 1, 1991

Standard, release 2.0. Reissued to include technical content updates. Due to the extent of the changes, revision bars are not used.

December 1994

Standard, release 3.0. Reissued for editorial changes. Due to the extent of the changes, revision bars are not used.

December 1995

Standard, release 4.0. Reissued for editorial changes.

Contents

About this document	1
References	1
Description	3
Physical description	4
Functional description	5
Software requirements	6
Operation	7
First tone detection	7
Specified tone detection	9
Special common carrier tone detection	9
Tandem tie trunk network dialing	9
Interactions	9

List of figures

Figure 1	
Jumper plug options	4